



**FORD KUGA: 1KVB744**

Vinnnumber:	<b>WF0AXXWPMAFE02951</b>	Versionname:	<b>2.0 TDCI 2WD 88KW TITANIUM</b>
First Registrationdate:	<b>10/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>116139</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>3232</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/55/17/103 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Vredestein: 5 mm</b>	Fr.R.	<b>Vredestein: 5 mm</b>
	Re.L.	<b>Hankook: 5 mm</b>	Re.R.	<b>Hankook: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>609,09</b>
-------------------	---------------

Alloy rim R L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------



Wing moulding F R, Scratch(es), E - Replace

14,40



Door panel R R, Scratch(es), Acceptable

0,00



Front compartment engine mounting, Tear, E - Replace

76,00



Wing F L, Scratch(es), Acceptable

0,00



Bumper trim R, Dent(s) and scratch(es), E - Replace

176,93



Bumper corner R L, Scratch(es), It - Spot repair

115,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Maintenance book, Missing, P - Check

0,00



Bumper moulding R, Scratch(es), E - Replace

14,40



Tailgate, Scratch(es), Acceptable

0,00



Door F L, Dent(s), Acceptable

0,00

