



BMW 5 TOURING: 1LLY096

Vinnumber:	WBA5L11040G323263	Versionname:	2.0 518D (100KW) TOURING
First Registrationdate:	23/10/2015	Fiscalpower:	
Expertise Mileage:	152278	Power Kw:	100
Bodytype:		Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2120
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	254,16
--------------------------	---------------

Bonnet, Chemical polution, Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display



Rear window, Not original part, Acceptable

0,00

No pictures to display

Bumper F, Hole, Le - Replace and paint

0,00

