



MERCEDES C: 1DUP143

Vinnumber:	WDD2042011F974748	Versionname:	C BRE 200 CDI BlueEFF. S&S 136PK
First Registrationdate:	3/09/2012	Fiscalpower:	
Expertise Mileage:	210091	Power Kw:	100
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1210
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 Y LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 2580,98

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rear window, Scratch(es), Acceptable

0,00

No pictures to display

Headlight L, Scratch(es), E - Replace

396,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Interior, Dirty, Cleaning

50,00




Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20

