



MERCEDES C: 1HX821

| | | | |
|------------------------------------|-------------------|--------------|-------------------------|
| Vinnumber: | WDD2050361F109126 | Versionname: | C BER 180 BlueTEC 116PK |
| First Registrationdate: | 17/10/2014 | Fiscalpower: | |
| Expertise Mileage: | 155242 | Power Kw: | 85 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3213 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-----------------------|
| Radio CD | Central consol F |
| Windows electric F | Front parking sensors |
| Windows electric R | Rear parking sensors |
| Cruise Control | Type of Tow bar |
| Steering wheel multifunctional | Tow bar fixed |
| Type of headlighting | Headlighting Halogen |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|----|---------------------|-----|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-------------------|-------|-------------------|
| 195/65/16/92 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Bridgestone: 5 mm | Fr.R. | Bridgestone: 5 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

Assistance equipment

| | | | |
|------------|-----|------------|-----|
| Repair kit | Yes | Compressor | Yes |
|------------|-----|------------|-----|

| | |
|-------------------|--------|
| Total cost ex VAT | 211,80 |
|-------------------|--------|

| | |
|------------------------------|------|
| Roof, Bad repair, Acceptable | 0,00 |
|------------------------------|------|



| | |
|--------------------------------|------|
| Bonnet, Bad repair, Acceptable | 0,00 |
|--------------------------------|------|



| | |
|--|------|
| Wheel cover F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Bad repair, Acceptable | 0,00 |



| | |
|---|--------|
| Wheel cover F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Deformed / Strained, LI - Repair and paint (complete) | 211,80 |



| | |
|---------------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Windscreen, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |