



MERCEDES A: 1KUK298

Vinnumber:	WDD1760111V085239	Versionname:	1.5 A 160 CDI
First Registrationdate:	7/07/2015	Fiscalpower:	
Expertise Mileage:	77470	Power Kw:	66
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	1732
Maintenance:	SINDS 27DAGEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1822,63
-------------------	----------------

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Door R L, Dent(s), PDR - Paintless dent repair

102,60



Floor covering F L, Burned, Smart repair

64,32



Sill trim R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

30,00



Roof, Dent(s), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

30,00



Ceiling, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Dent(s), PDR - Paintless dent repair

82,80



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing R, Scratch(es), E - Replace

49,60



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Maintenance, Maintenance, Execute

0,00



Ignition key, Missing, E - Replace

150,00

No pictures to display

Covering interior A pillar L, Burned, E - Replace

39,60



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wheel cover R L, Scratch(es), E - Replace

30,00



Door panel R L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace

30,00



Internal Boot Lining R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), It - Spot repair

115,56



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80





Boot cover, Tear, Acceptable

0,00

No pictures to display