



**RENAULT CLIO: 1LLY705**

Vinnumber:	<b>VF15R0J0A53968372</b>	Versionname:	<b>1.5 ENERGY DCI 90E EXPRESSION</b>
First Registrationdate:	<b>23/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>95705</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2513</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/92 T Steel</b>			
Summer tyres:	Fr.L.	<b>Vredestein: 5 mm</b>	Fr.R.	<b>Vredestein: 5 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

<b>Total cost ex VAT</b>	<b>657,74</b>
--------------------------	---------------

<b>Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>254,68</b>
--	---------------



<b>Bumper R, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

Wheel cover F L, Broken, E - Replace

24,00



Wing R L, Dent(s), Acceptable

0,00

*No pictures to display*

Wing R R, Dent(s), Acceptable

0,00

*No pictures to display*

Backrest cover F R, Stain, Cleaning

25,00



Seat cover F R, Stain, Cleaning

25,00



Wheel cover R L, Scratch(es), E - Replace

24,00



Ignition key, Missing, E - Replace

0,00



Wheel cover F R, Scratch(es), E - Replace

24,00



Wheel cover R R, Scratch(es), E - Replace

24,00





Seat cover F L, Stain, Cleaning 25,00



Bonnet, Dent(s), LI - Repair and paint (complete) 232,06



Rocker panel inner R R, Dent(s), Acceptable 0,00

*No pictures to display*

Bumper F, Scratch(es), Acceptable 0,00

*No pictures to display*