



VOLKSWAGEN GOLF VARIANT: 1JJU035

Vinnumber:	WVWZZZAUZFP580316	Versionname:	1.6 CR TDI 77KW DSG BMT TRENDLINE
First Registrationdate:	6/01/2015	Fiscalpower:	
Expertise Mileage:	122048	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3123
Maintenance:	BINNEN 8400 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 M-S Steel			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2842,44
--------------------------	----------------

Internal Boot Lining L, Broken, E - Replace	48,30
--	--------------



Boot carpet, Missing, E - Replace

100,00



Wheel cover F L, Missing, E - Replace

30,00



Seat cover F R, Dirty, Cleaning

25,00



Wing F L, Chemical polution, LI - Repair and paint (complete)

220,18



Trunk lid covering R, Scratch(es), Smart repair

110,64



Seat cover F L, Dirty, Cleaning

25,00



Wheel cover R R, Missing, E - Replace

30,00



Seat cover R R, Dirty, Cleaning

25,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Seat cover R L, Dirty, Cleaning

25,00



Door panel R R, Hole, Smart repair

110,64



Boot carpet, Dirty, Cleaning

25,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Internal Boot Lining R, Broken, E - Replace

48,30



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

301,68



Bumper F, Scratch(es), LI - Repair and paint (complete)


211,80



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Armrest F Mid, Tear, Smart repair 64,32



Ignition key, Missing, E - Replace 150,00



Steering wheel, Worn, Acceptable 0,00

No pictures to display