


VOLKSWAGEN Passat: 1HLK879

Vinnumber:	WVWZZZ3CZEE159282	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	20/08/2014	Fiscalpower:	
Expertise Mileage:	169863	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2224
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Front parking sensors	
Seats F heated	Rear parking sensors	
Radio multimedia	Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/97 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 0 mm	Fr.R.
	Re.L.	Dunlop: 7 mm	Re.R.
			Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			327,36
Bonnet, Dent(s), Le - Replace and paint			0,00



Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Maintenance book, Missing, E - Replace	0,00
No pictures to display	
Windscreen, Scratch(es), E - Replace	0,00



Wing R R, Dent(s), Acceptable	0,00
No pictures to display	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display	