



## VOLVO V60: 1HLU443

|                                    |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber:                         | <b>YV1FW8481F1230861</b> | Versionname: | <b>V60 BRE D2 Kinetic 115PK</b> |
| First Registrationdate:            | <b>22/08/2014</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                 | <b>120978</b>            | Power Kw:    | <b>84</b>                       |
| Bodytype:                          |                          | Body color:  | <b>Red</b>                      |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Opaque</b>                   |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Maintenance:                       | <b>IN 6455 KM</b>        | Parking lot: | <b>3813</b>                     |
| Maintenance:                       | <b>OK</b>                |              |                                 |
| Battery functioning:               | <b>Yes</b>               |              |                                 |
| Number of doors:                   | <b>5</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>5</b>                 |              |                                 |
| Rims summer:                       | <b>Aluminium</b>         |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                 |

## Options

|                                |                              |                      |                      |
|--------------------------------|------------------------------|----------------------|----------------------|
| Radio CD                       |                              | Central consol F     |                      |
| GPS storage                    | <b>HD</b>                    | Luggage cover        |                      |
| GPS storage                    |                              | Rear parking sensors |                      |
| Windows electric F             |                              | Type of Tow bar      | <b>Tow bar fixed</b> |
| Windows electric R             |                              |                      |                      |
| Cruise Control                 |                              |                      |                      |
| Steering wheel multifunctional |                              |                      |                      |
| Radio multimedia               |                              |                      |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                      |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |                      |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>205/60/16/92 H LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Uniroyal: 5 mm</b> | Fr.R. | <b>Uniroyal: 5 mm</b> |
|                                  | Re.L. | <b>Uniroyal: 5 mm</b> | Re.R. | <b>Uniroyal: 5 mm</b> |

## Assistance equipment

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 361,40 |
|-------------------|--------|

|                               |      |
|-------------------------------|------|
| Door R L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

|  |       |
|--|-------|
| Engine protective plate, Hole, E - Replace | 54,60 |
|--|-------|



Bumper F, Stone chip(s), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Repaired, Acceptable 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Repaired, P - Check 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Repaired, P - Check 0,00

