



**VOLKSWAGEN Transporter: 1ELI254**

Vinnumber:	<b>WV1ZZZ7HZDH038252</b>	Versionname:	<b>TRANSP.1200 B/F SWB 84PK</b>
First Registrationdate:	<b>14/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>136134</b>	Power Kw:	<b>62</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2227</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining artificial leather</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/65/16/105 T Steel</b>				
Summer tyres:	Fr.L.	<b>Semperit: 7 mm</b>	Fr.R.	<b>Semperit: 7 mm</b>
	Re.L.	<b>Semperit: 8 mm</b>	Re.R.	<b>Semperit: 8 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	623,42
-------------------	--------

Bumper R, Chemical pollution, Acceptable	0,00
--	------

No pictures to display

Trunk lid covering R, Broken, E - Replace	39,40
---	-------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Bumper F, Chemical polution, Acceptable	0,00
---	------

*No pictures to display*

Bodywork, Not original part, Remove lettering	0,00
---	------

*No pictures to display*

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	434,02
---	--------



Rearview mirror R complete, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Roof pillar L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Rearview mirror L complete, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*