



VOLKSWAGEN PASSAT: 1RFY224

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber: | WVWZZZ3CZHE106334 | Versionname: | 1.6 TDI MSQ COMFORTLINE |
| First Registrationdate: | 14/12/2016 | Fiscalpower: | |
| Expertise Mileage: | 180530 | Power Kw: | 88 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2210 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Windows electric F | Central consol F |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | Type of Tow bar |
| Radio multimedia | No Tow bar |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|---------------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | NOT OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------|-------|--------------------|
| 215/60/16/95 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Other: 1 mm | Fr.R. | Other: 1 mm |
| | Re.L. | Other: 3 mm | Re.R. | Other: 3 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

Total cost ex VAT 0,00

Roof, Chemical polution, Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display