



**VOLKSWAGEN GOLF VII: 1LNB513**

|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber:                         | <b>WVWZZZAUZGP052127</b> | Versionname: | <b>1.6 TDI 81KW TRENDLINE</b> |
| First Registrationdate:            | <b>26/10/2015</b>        | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>178023</b>            | Power Kw:    | <b>81</b>                     |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                   |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                  |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>2123</b>                   |
| Battery functioning:               | <b>Yes</b>               |              |                               |
| Number of doors:                   | <b>5</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Steel</b>             |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Central consol F      |                   |
| GPS storage                    | <b>SD</b>                    | Luggage cover         |                   |
| GPS storage                    |                              | Front parking sensors |                   |
| Windows electric F             |                              | Rear parking sensors  |                   |
| Cruise Control                 |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Steering wheel multifunctional |                              |                       |                   |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                          |       |                          |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
|               | <b>195/65/15/91 H Steel</b> |                          |       |                          |
| Summer tyres: | Fr.L.                       | <b>Goodyear: 3 mm</b>    | Fr.R. | <b>Goodyear: 3 mm</b>    |
|               | Re.L.                       | <b>Bridgestone: 4 mm</b> | Re.R. | <b>Bridgestone: 4 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>795,36</b> |
|-------------------|---------------|

|                                       |             |
|---------------------------------------|-------------|
| Windscreen, Stone chip(s), Acceptable | <b>0,00</b> |
|---------------------------------------|-------------|

*No pictures to display*

|                                |             |
|--------------------------------|-------------|
| Wing F L, Repaired, Acceptable | <b>0,00</b> |
|--------------------------------|-------------|



Rear spoiler, Hail damage, PDR - Hail 0,00



Maintenance, Maintenance, P - Check 0,00



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar R, Hail damage, PDR - Hail 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, Not original part, E - Replace 0,00



Roof, Hail damage, PDR - Hail 0,00



Door R L, Scratch(es), It - Spot repair 115,56



Wing F R, Hail damage, PDR - Hail 0,00



Wing R L, Scratch(es), It - Spot repair 115,56



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper trim R, Scratch(es), Smart repair 110,64



Wheel cover F R, Broken, E - Replace 30,00



Bonnet, Hail damage, PDR - Hail 0,00



Door F L, Repaired, Acceptable 0,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

*No pictures to display*

Wheel cover R L, Scratch(es), Acceptable 0,00

*No pictures to display*