



VOLVO V60: 1LPK530

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber: | YV1FW79C1G1306761 | Versionname: | 2.0 D3 VOLVO OCEAN RACE |
| First Registrationdate: | 5/11/2015 | Fiscalpower: | |
| Expertise Mileage: | 70513 | Power Kw: | 110 |
| Bodytype: | | Body color: | Dark Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1413 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Type of Tow bar |
| Cruise Control | No Tow bar |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 235/40/18/95 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

Assistance equipment

| | | | |
|------------------------------------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

Total cost ex VAT 1114,25

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), E - Replace

0,00



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete)

348,09



Door panel R L, Scratch(es), E - Replace

132,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



