



VOLVO V60: 1KVD275

Vinnumber:	YV1FW78C0G1293915	Versionname:	2.0 D2 GEARTRONIC KINETIC
First Registrationdate:	10/07/2015	Fiscalpower:	
Expertise Mileage:	146217	Power Kw:	88
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3225
Maintenance:	5052KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/97 V LightMetal				
Summer tyres:	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1194,70
-------------------	----------------

Interior, Dirty, Cleaning	100,00
---------------------------	---------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door panel F L, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), 67 - Polish 0,00



Bonnet, Scratch(es), 67 - Polish 0,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 406,50

