



VOLVO XC60: 1LEG967

Vinnumber:	VV1DZARC1G2815507	Versionname:	2.0 D3 2WD KINETIC
First Registrationdate:	4/09/2015	Fiscalpower:	
Expertise Mileage:	143962	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 5098 KM	Parking lot:	3703
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/17/108 V LightMetal				
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1157,55
-------------------	----------------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Mirror side blinker L, Broken, E - Replace	31,20
--	--------------



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Wing R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Dashboard, Glue residues, Cleaning

25,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Outer valance R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Seat cover F R, Stain, Cleaning

25,00



Door panel F L, Hole, Smart repair

110,64



Door F L, Dent(s) and scratch(es), It - Spot repair

115,56



Bumper spoiler F, Dent(s) and scratch(es), E - Replace

48,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Seat cover F L, Stain, Cleaning

25,00



Central pillar L, Scratch(es), E - Replace

58,27



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display