



AUDI A3 SPORTBACK: 1JVL899

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | WAUZZZ8V8FA126754 | Versionname: | 1.6 TDI ULTRA ATTRACTION SPORTBACK |
| First Registrationdate: | 6/03/2015 | Fiscalpower: | |
| Expertise Mileage: | 116207 | Power Kw: | 81 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4733 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | HD | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|---------------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | NOT OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-------------------------|-------|-------------------------|
| 205/55/16/91 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Michelin: 1,6 mm | Fr.R. | Michelin: 1,6 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | | | |
|--|------------|------------|----------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 1565,08 |
| Door R R, Dent(s), PDR - Paintless dent repair | | | 63,00 |



Seat cover R, Stain, Cleaning

25,00



Boot carpet, Stain, Cleaning

25,00



Sill outer R, Scratch(es), LI - Repair and paint (complete)

310,50




Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display


Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Rear window, Scratch(es), E - Replace

370,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Bodywork, Not original part, Remove lettering

0,00

No pictures to display

Bumper F L, Scratch(es), Acceptable

0,00

No pictures to display

No pictures to display