



**MERCEDES A: 1JFU002**

Vinnumber:	<b>WDD1760111V040456</b>	Versionname:	<b>A 160 CDI 90PK</b>
First Registrationdate:	<b>5/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>178482</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4332</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/91 T Steel</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>457,80</b>
<b>Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>			<b>211,80</b>





Wheel cover F R, Scratch(es), E - Replace 30,00



Boot cover, Scratch(es), Acceptable 0,00

No pictures to display


Bumper F R, Repaired, Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 30,00



Roof pillar R, Dent(s), PDR - Paintless dent repair 63,00



Wheel cover F L, Missing, E - Replace 30,00



Wheel cover R L, Scratch(es), E - Replace 30,00



Roof pillar L, Dent(s), PDR - Paintless dent repair 63,00



Door panel F L, Worn, Acceptable 0,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Armrest lid F Mid, Worn, Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display