



MINI : 1PCU661

Vinnumber:	WMWXN110X03B51639	Versionname:	1.5 ONE D
First Registrationdate:	7/06/2016	Fiscalpower:	
Expertise Mileage:	129502	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3129
Battery functioning:	Yes		
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

175/65/15/84 H LightMetal				
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3318,01
Roof, Scratch(es), LI - Repair and paint (complete)	481,50



Wheel hub cap F L, Missing, E - Replace 20,00



Bumper F R, Scratch(es), It - Spot repair 115,56



Ceiling, Hole, Smart repair 64,32



Wheel arch cover R R, Deformed / Strained, E - Replace 35,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), E - Replace 370,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

Wing L, R, Scratch(es), LI - Repair and paint (complete)

53,00



Bumper R, Dent(s) and scratch(es), Le - Replace and paint

651,00



Ignition key, Missing, E - Replace

150,00



Wheel hub cap R R, Missing, E - Replace

20,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,35




Wheel hub cap F R, Missing, E - Replace

20,00



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

386,08





Wheel hub cap R L, Missing, E - Replace

20,00



Bodywork, Glue residues, Acceptable

0,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Seat cover F R, Stain, Cleaning

25,00



Rear spoiler, Chemical pollution, 67 - Polish

0,00



Tailgate, Scratch(es), 67 - Polish

0,00

No pictures to display