


**OPEL ANTARA: 1PSX385**

Vinnumber:	<b>WOLLV6HXFB065188</b>	Versionname:	<b>2.2 CDTI 120KW 4X2 S/S ENERGY</b>
First Registrationdate:	<b>30/12/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>166001</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3720</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/65/17/104 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Hankook: 4 mm</b>	Re.R.	<b>Hankook: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT		1576,95
Trunk lid covering R, Scratch(es), E - Replace		171,10



Bonnet, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
License plate F, Deformed / Strained, E - Replace	33,95



Roof, Hail damage, PDR - Hail	0,00
-------------------------------	------



Outer door handle F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s), LI - Repair and paint (complete)	318,35



Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	366,35



Wing trim R R, Scratch(es), E - Replace	0,00
---	------



Bumper R, Scratch(es), E - Replace	415,20
------------------------------------	--------



Door moulding Lower R R, Scratch(es), E - Replace	114,00
---	--------



Wing R R, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Dent(s), Acceptable

0,00

*No pictures to display*

Tailgate, Dent(s), Acceptable

0,00

*No pictures to display*

Door F R, Dent(s), Acceptable

0,00

*No pictures to display*