


OPEL Insignia: 1FU0318

Vinnumber:	WOLGT8ER8E1015261	Versionname:	INSIGNIA BRE ecoFLEX Cosmo 120PK
First Registrationdate:	29/10/2013	Fiscalpower:	
Expertise Mileage:	170122	Power Kw:	88
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1306
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	742,11
-------------------	--------

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper F, Repaired, Acceptable 0,00

No pictures to display

Door F R, Scratch(es), It - Spot repair 115,56



Rear window, Scratch(es), E - Replace 0,00

