



AUDI a3 Limousine: UK8799

Vinnumber:	WAUZZZ8V4J1034078	Versionname:	1.0 TFSI 85kw
First Registrationdate:	22/11/2017	Fiscalpower:	
Expertise Mileage:	59801	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	DANS 200 KMS OU 403 JOURS	Parking lot:	3422
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F		Night vision	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Alarm			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


205/55/16/91 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			427,16
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Door R L, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), It - Spot repair 115,56



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Front compartment engine mounting, Tear, E - Replace 58,60

