



BMW 3 TOURING: 1KUY487

Vinnumber:	WBA3K11040F840529	Versionname:	2.0 318D (105KW) TOURING
First Registrationdate:	9/07/2015	Fiscalpower:	
Expertise Mileage:	128188	Power Kw:	105
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 18000 KM	Parking lot:	4504
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	756,86
-------------------	---------------

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Seat cover F L, Tear, Acceptable	0,00
----------------------------------	-------------

No pictures to display


Wing F R, Dent(s), LI - Repair and paint (complete)

220,18



Rear window, Scratch(es), E - Replace

0,00



Wing F L, Scratch(es), It - Spot repair

115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper cover R M, Dent(s) and scratch(es), It - Spot repair

115,56



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F L, Scratch(es), It - Spot repair

115,56

