



BMW 1 HATCH: 1SYJ780

Vinnumber:	WBA1V710405A66308	Versionname:	116d (85 kW)
First Registrationdate:	18/08/2017	Fiscalpower:	
Expertise Mileage:	21387	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3827
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	63,00
Bonnet, Dent(s), PDR - Paintless dent repair	63,00



Roof pillar R, Dent(s), Acceptable	0,00
------------------------------------	------

No pictures to display

Roof, Dent(s), Acceptable	0,00
---------------------------	------

No pictures to display

Wing F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Rear window, Not original part, Acceptable	0,00
--	------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display