



ALFA ROMEO Mito: 1CQB513

| | | | |
|-------------------------|--------------------------|--------------|---|
| Vinnumber: | ZAR95500001185810 | Versionname: | MITO BER Distinctive St&St DPF 115PK |
| First Registrationdate: | 31/01/2012 | Fiscalpower: | |
| Expertise Mileage: | 140443 | Power Kw: | 85 |
| Bodytype: | | Body color | Dark Brown |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Front | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 2811 |
| Number of doors | 3 | | |
| Number of seats | 4 | | |
| Number head rests | 4 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |

Options

| | | | |
|--------------------------------|-------------------------------|----------------------|-------------------|
| Radio CD | | Luggage cover | |
| Windows electric F | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | No Tow bar |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | No GPS | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|---------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | NOT OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 215/45/17/87 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (normal) | 0 |
| Number of charging cables (rapid charge) | 0 |

| | |
|--|----------------|
| Total cost ex VAT | 2346,20 |
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 342,56 |



| | |
|--|---------------|
| Sill outer L, Dent(s), LI - Repair and paint (complete) | 248,40 |
|--|---------------|



Moulding windscreen U, Broken, E - Replace

74,00



Rearview mirror housing L, Scratch(es), Smart repair

110,64



Ignition key, Missing, E - Replace

150,00

No pictures to display

Sill outer R, Dent(s), LI - Repair and paint (complete)

248,40



Wing R L, Scratch(es), LI - Repair and paint (complete)

246,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Chemical pollution, LI - Repair and paint (complete)

232,06



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Dent(s), PDR - Paintless dent repair

63,00



Wing F R, Chemical polution, LI - Repair and paint (complete)

176,14



Bumper F, Dent(s), LI - Repair and paint (complete)

169,44

