



| | | | |
|------------------------------------|--------------------------|--------------|---|
| DS 4: 1LHT199 | | | |
| Vinnumber: | VF7NXBHXMFY552539 | Versionname: | 1.6 BLUEHDI 115 BUSINESS GPS & LEATHER |
| First Registrationdate: | 1/10/2015 | Fiscalpower: | |
| Expertise Mileage: | 75312 | Power Kw: | 85 |
| Bodytype: | Hatchback | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2212 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| | | | |
|--------------------------------|---------------------------------------|----------------------|--------------------------|
| Options | | | |
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | HD | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | Tow bar removable |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining semi-artificial leather | | |
| Type of climate control | Autom climate control | | |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|----------------------------------|----------------------|-------|----------------------|
| Degree of wear | | | | |
| | 215/55/17/98 V LightMetal | | | |
| Summer tyres: | Fr.L. | Pirelli: 3 mm | Fr.R. | Pirelli: 3 mm |
| | Re.L. | Pirelli: 6 mm | Re.R. | Pirelli: 6 mm |

| | | | |
|-----------------------------|------------|------|------------|
| Assistance equipment | | | |
| Emergency spare wheel | Yes | Jack | Yes |

| | |
|-------------------|---------------|
| Total cost ex VAT | 360,56 |
|-------------------|---------------|

| | |
|--|-------------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
|--|-------------|

No pictures to display

| | |
|------------------------------------|---------------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|---------------|

No pictures to display

| | |
|-------------------------------|-------------|
| Door R L, Dent(s), Acceptable | 0,00 |
|-------------------------------|-------------|

No pictures to display

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), It - Spot repair 115,56

