


**BMW 3 GRAN TURISMO: JD6278**

|                                    |                          |              |   |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber:                         | <b>WBA3Y51060D982169</b> | Versionname: | <b>2.0 320D XDRIVE 4WD (135KW) GRAN TURISMO</b> |
| First Registrationdate:            | <b>9/04/2015</b>         | Fiscalpower: |   |
| Expertise Mileage:                 | <b>137837</b>            | Power Kw:    | <b>135</b>                                      |
| Bodytype:                          |                          | Body color:  | <b>Black</b>                                    |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                                  |
| Transmission:                      | <b>4 Weel</b>            | Rims summer: | <b>Aluminium</b>                                |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                       |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2118</b>                                     |
| Number of doors:                   | <b>5</b>                 |              |   |
| Number of seats:                   | <b>5</b>                 |              |   |
| Number head rests:                 | <b>5</b>                 |              |   |
| Rims summer:                       | <b>Aluminium</b>         |              |   |
| Category:                          | <b>Passenger Car</b>     |              |   |
| Oil level:                         | <b>OK</b>                |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |   |

**Options**

|                                |                                  |                      |                   |
|--------------------------------|----------------------------------|----------------------|-------------------|
| Radio CD                       |                                  | Central consol F     |                   |
| Windows electric F             |                                  | Luggage cover        |                   |
| Windows electric R             |                                  | Rear parking sensors |                   |
| Cruise Control                 |                                  | Type of Tow bar      | <b>No Tow bar</b> |
| Steering wheel multifunctional |                                  |                      |                   |
| Seats F heated                 |                                  |                      |                   |
| Radio multimedia               |                                  |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>      |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>      |                      |                   |
| Type of Lining                 | <b>Lining artificial leather</b> |                      |                   |
| Type of climate control        | <b>Autom climate control</b>     |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                      |       |                      |
|---------------|----------------------------------|----------------------|-------|----------------------|
|               | <b>225/55/17/97 H LightMetal</b> |                      |       |                      |
| Winter tyres: | Fr.L.                            | <b>Pirelli: 2 mm</b> | Fr.R. | <b>Pirelli: 2 mm</b> |
|               | Re.L.                            | <b>Pirelli: 3 mm</b> | Re.R. | <b>Pirelli: 3 mm</b> |

**Assistance equipment**

|  |          |         |            |
|--|----------|---------|------------|
| Number of charging cables (normal)       | <b>0</b> | Runflat | <b>Yes</b> |
| Number of charging cables (rapid charge) | <b>0</b> |         |            |

|   |               |
|---|---------------|
| Total cost ex VAT   | <b>625,15</b> |
| Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) | <b>318,35</b> |



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bonnet, Chemical polution, Acceptable

0,00

*No pictures to display*