



BMW 3 GRAN TURISMO: 1KXB862

Vinnumber:	WBA3Y11080D903318	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	20/07/2015	Fiscalpower:	
Expertise Mileage:	119178	Power Kw:	100
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3504
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	439,12
-------------------	--------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Backrest cover F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Seat cover F L, Scratch(es), Smart repair	64,32
---	-------



Sill outer L, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Windscreen, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Seat cover R L, Incomplete, Repair/replace (lump sum)	5,00
---	------



Centre console, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display