


BMW X1: 1RGE780

Vinnumber:	WBAHT710205G69925	Versionname:	2.0 SDRIVE18D (100KW)
First Registrationdate:	15/12/2016	Fiscalpower:	
Expertise Mileage:	87783	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1709
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	449,08
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	386,08



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair	63,00
--	-------

