



SKODA Octavia: 1HYJ720

Vinnumber:	TMBJG7NE1F0100923	Versionname:	OCTAVIA COMBI Ambition 105PK
First Registrationdate:	29/10/2014	Fiscalpower:	
Expertise Mileage:	111347	Power Kw:	77
Bodytype:		Body color:	Light Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3404
Maintenance:	IN 8700 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats R heated	
GPS storage	SD	Sun Roof electric	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 335,00

Roof carpet, Stein, Chemical cleaning 25,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00



Windscreen, Stone chip(s), Windscreen repair

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Floor covering F L, Tear, Acceptable

0,00



Wing F R, Scratch(es), Acceptable

0,00



Seat cover R, Stain, Cleaning

25,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

