



FORD TRANSIT: CM7198

Vinnumber:	WF0DXXTTGDFJ49076	Versionname:	2.2TDCI 92KW AMBIENTE RWD 350L
First Registrationdate:	23/10/2015	Fiscalpower:	
Expertise Mileage:	148923	Power Kw:	92
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV03
Number of doors:	2		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Steering wheel multifunctional	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/16/115 R Steel			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	30,00
-------------------	-------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------



Rocker panel inner F L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side blinker L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Acceptable 0,00



Wheel hub cap F L, Missing, E - Replace 15,00



Rearview mirror L complete, Scratch(es), Acceptable 0,00

No pictures to display

Wheel hub cap F R, Missing, E - Replace 15,00



Bodywork, Scratch(es), Acceptable 0,00

No pictures to display