



MERCEDES C COUP?: ZM8114

Vinnumber:	WDD2053401F644957	Versionname:	C 180
First Registrationdate:	9/10/2017	Fiscalpower:	
Expertise Mileage:	45231	Power Kw:	115
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	B1 DANS 18 JOURS	Parking lot:	3820
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Alarm			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Level control			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/18/95 Y LightMetal				
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	299,36
-------------------	---------------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Mirror side blinker L, Broken, E - Replace

30,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L polished, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair

58,80



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror basis L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56

