


PEUGEOT PARTNER TEPEE: 1KU5741

Vinnumber:	VF37JBHY6FJ709247	Versionname:	1.6 BLUEHDI 73KW S/S TEPEE OUTDOOR
First Registrationdate:	8/07/2015	Fiscalpower:	
Expertise Mileage:	142021	Power Kw:	73
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3601
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/15/94 T Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3361,95
Wing R R, Scratch(es), LI - Repair and paint (complete)	231,15



Windscreen, Stone chip(s), Windscreen repair

58,80



Bumper F R, Scratch(es), It - Spot repair

115,56



Side window R L, Scratch(es), E - Replace

287,62



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Door moulding Lower F L, Scratch(es), E - Replace

91,50



Bumper F, Scratch(es), E - Replace

398,40



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)

238,76



Wing R L, Scratch(es), LI - Repair and paint (complete)

231,15



Sill outer R, Scratch(es), E - Replace

141,01



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Door moulding Lower F R, Scratch(es), E - Replace 91,50



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 458,02



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 334,76



Door R L, Scratch(es), LI - Repair and paint (complete) 238,76



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), E - Replace 329,40



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display