



**MERCEDES CLA SHOOTING BRAKE: 1LKL933**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>WDD1179021N291784</b> | Versionname: | <b>2.1 CLA 200 CDI 4MATIC SHOOTING BRAKE</b> |
| First Registrationdate:            | <b>13/10/2015</b>        | Fiscalpower: |  |
| Expertise Mileage:                 | <b>68808</b>             | Power Kw:    | <b>100</b>                                   |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                                  |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                               |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                             |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                    |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>1333</b>                                  |
| Battery functioning:               | <b>Yes</b>               |              |  |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>5</b>                 |              |  |
| Number head rests:                 | <b>1</b>                 |              |  |
| Rims summer:                       | <b>Aluminium</b>         |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                               |                   |
|--------------------------------|-------------------------------|-------------------|
| Radio CD                       |                               | Sun Roof electric |
| GPS storage                    | <b>SD</b>                     | Panoramic roof    |
| GPS storage                    |                               | Central consol F  |
| Windows electric F             |                               | Luggage cover     |
| Windows electric R             |                               |                   |
| Cruise Control                 |                               |                   |
| Steering wheel multifunctional |                               |                   |
| Radio multimedia               |                               |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>     |                   |
| Type of GPS                    | <b>GPS big screen color</b>   |                   |
| Type of Lining                 | <b>Lining leather</b>         |                   |
| Type of climate control        | <b>Manual climate control</b> |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>205/55/16/91 V LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|                                  | Re.L. | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

Total cost ex VAT 261,80

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning

25,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Seat cover F R, Stain, Cleaning

25,00

