



SEAT Alhambra: 1JFU911

Vinnnummer:	VSSZZZ7NZFV505825	Versionname:	ALHAMBRA E-Ecom.Busin.Limit.115PK
First Registrationdate:	5/12/2014	Fiscalpower:	
Expertise Mileage:	149559	Power Kw:	85
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3332
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H Steel				
Summer tyres:	Fr.L.	Kleber: 3 mm	Fr.R.	Kleber: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm


Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1690,36
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Dent(s), Acceptable	0,00
No pictures to display	

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Rear window, Scratch(es), E - Replace

0,00



Mirror side blinker R, Broken, E - Replace

31,20



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Mirror side blinker L, Broken, E - Replace 31,20



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display


Headlight L, Waterinfiltration, Acceptable 0,00



Door R L, Repaired, Acceptable 0,00

No pictures to display

Internal Boot Lining L, Broken, E - Replace 10,00



Wheel cover F L, Missing, E - Replace 36,00



Wing R L, Repaired, Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Missing, E - Replace 36,00



Door F L, Repaired, Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Reflector, Broken, E - Replace 54,00



Wheel cover R R, Missing, E - Replace 36,00

