



TOYOTA PRIUS: 11LA239

Vinnumber:	JTDKN36U401983085	Versionname:	1.8 VVT-I HYBRID COMFORT AUTO
First Registrationdate:	16/10/2015	Fiscalpower:	
Expertise Mileage:	43629	Power Kw:	100
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	4102
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Head-up Display	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	195/65/15/91 M-S Steel			
	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1805,81
-------------------	----------------

Roof, Dent(s), Acceptable	0,00
---------------------------	-------------

No pictures to display

Wing R L, Scratch(es), It - Spot repair	115,56
---	---------------



Wheel cover F L, Missing, E - Replace

30,00



Wheel cover F R, Broken, E - Replace

30,00



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

30,00



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Engine protective plate, Broken, E - Replace

231,62



Wing F L, Chemical pollution, LI - Repair and paint (complete)

220,18



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 259,80

