


VOLVO V40: 1LSY355

Vinnumber:	VV1MV74L1G2311341	Versionname:	2.0 D2-82 KINETIC
First Registrationdate:	26/11/2015	Fiscalpower:	
Expertise Mileage:	76885	Power Kw:	88
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2613
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	766,50
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00




Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Scratch(es), LI - Repair and paint (complete)

481,50



Wing R R, Bad repair, P - Check

0,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), 67 - Polish

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

