


TOYOTA AVENSIS TOURING SPORTS: 1PNU968

Vinnumber:	SB1EN76L00E012416	Versionname:	1.6 D-4D COMFORT
First Registrationdate:	17/08/2016	Fiscalpower:	
Expertise Mileage:	54937	Power Kw:	82
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Body color:	BLAUW
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	GEEN MELDING	Oil level:	OK
Maintenance:	OK	Parking lot:	2826
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-Alcantara	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	683,43
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35




Rear spoiler, Chemical polution, 67 - Polish 0,00




Rear wiper blade, Damaged, E - Replace 25,00



Roof pillar R, Bad repair, P - Check 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 50,00





Wing F R, Bad repair, P - Check

0,00



Door R R, Bad repair, P - Check

0,00



Roof, Chemical polution, 67 - Polish

0,00



Wing R R, Bad repair, P - Check

0,00

