



VOLKSWAGEN GOLF VII: 1LPD584

Vinnumber:	VWVZZZAUZGW153174	Versionname:	1.6 TDI 81KW TRENDLINE
First Registrationdate:	3/11/2015	Fiscalpower:	
Expertise Mileage:	124897	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3533
Maintenance:	ONDERHOUD REEDS GEDAAN , MAAR RESET NIET VERGETEN DOOR DE GGE...OVBH		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	553,80
-------------------	---------------

Roof, Scratch(es), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Maintenance, Maintenance, P - Check	0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wheel aperture R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F R, Stain, Cleaning	25,00



Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	30,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Seat cover R R, Stain, Cleaning	25,00
---------------------------------	-------



Moulding windscreen R, Missing, E - Replace	20,20
---	-------



Wheel cover R L, Scratch(es), E - Replace	30,00
---	-------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display