



VOLKSWAGEN GOLF VII: 1LSJ160

Vinnumber:	WVWZZZAUZGW152991	Versionname:	1.6 TDI 81KW TRENDLINE
First Registrationdate:	23/11/2015	Fiscalpower:	
Expertise Mileage:	69716	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1119
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	557,98
-------------------	---------------

Door panel F L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Wing R R, Chemical polution, Acceptable

0,00

No pictures to display

Wing R L, Dent(s), PDR - Paintless dent repair

63,00



Door R L, Dent(s), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace

0,00



Door F R, Dent(s), PDR - Paintless dent repair

63,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner F R, Dent(s), Acceptable

0,00

No pictures to display

Rearview mirror L complete, Scratch(es), Acceptable

0,00

No pictures to display

Door panel R R, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Not original part, Acceptable

0,00

No pictures to display

Bumper F, Stone chip(s), Acceptable

0,00

No pictures to display