



## VOLKSWAGEN POLO: 1JUJ928

Vinnumber:	WVWZZZ6RZFY250200	Versionname:	1.4 TDI 66KW TRENDLINE BMT
First Registrationdate:	27/02/2015	Fiscalpower:	
Expertise Mileage:	102893	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3411
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

## Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

## Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

## Degree of wear

	<b>175/70/14/84 T Steel</b>			
Summer tyres:	Fr.L.	Firestone: 1 mm	Fr.R.	Firestone: 1 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

## Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	202,56
Wing R L, Dent(s), Acceptable	0,00
No pictures to display	
Bumper F, Scratch(es), It - Spot repair	115,56



Tyre F L, Worn, Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00



Wheel cover F R, Scratch(es), E - Replace 24,00



Tyre F R, Worn, Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display