



**AUDI A6: 1JAH708**

Vinnumber:	<b>WAUZZZ4G1EN204984</b>	Versionname:	
First Registrationdate:	<b>17/11/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>91934</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2204</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/60/16/98 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Vredestein: 5 mm</b>	Fr.R.	<b>Vredestein: 5 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>2290,29</b>
<b>Bonnet, Chemical polution, 67 - Polish</b>	<b>0,00</b>



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Wing F L, Scratch(es), LI - Repair and paint (complete)

264,21



Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84



Ceiling, Damaged, E - Replace

564,00



Windscreen, Repaired, E - Replace

560,64

*No pictures to display*

Bumper R, Scratch(es), 67 - Polish

0,00



Door R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim F R, Scratch(es), E - Replace

277,44



Wing R R, Scratch(es), Acceptable

0,00

*No pictures to display*