


RENAULT Kangoo Express: 1GNZ187

Vinnnummer:	VF1FW18B550667853	Versionname:	KANGOO EXPR.B/F Gr.Confort 90PK
First Registrationdate:	21/03/2014	Fiscalpower:	
Expertise Mileage:	123440	Power Kw:	66
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4120
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Summer tyres:	Fr.L.	BF Goodrich: 5 mm	Fr.R.	BF Goodrich: 5 mm
	Re.L.	BF Goodrich: 5 mm	Re.R.	BF Goodrich: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	703,90
Internal Boot Lining R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk door R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Steering wheel, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F L, Scratch(es), Acceptable	0,00

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Broken, E - Replace 22,50



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Deformed / Strained, E - Replace 398,40



Bodywork, Not original part, Acceptable 0,00



Trunk door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 250,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00

No pictures to display

Windscreen, Crack, E - Replace 0,00



Inner door handle F L, Broken, E - Replace 33,00

