



FORD GRAND C-MAX: 1JJR589

Vinnumber:	WFOHXXGCBHEG54697	Versionname:	1.6 TDCI 85 KW S/S TREND
First Registrationdate:	6/01/2015	Fiscalpower:	
Expertise Mileage:	56091	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4706
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		







Total cost ex VAT	791,54
--------------------------	---------------

Roof, Chemical polution, 67 - Polish	0,00
---	-------------

<i>No pictures to display</i>	
-------------------------------	--

Sliding door L, Dent(s), Acceptable	0,00
--	-------------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover R, Stain, Cleaning	25,00
	
Wing R R, Scratch(es), It - Spot repair	115,56
	
Rear window, Scratch(es), Acceptable	0,00
	
Protection plate M, Deformed / Strained, E - Replace	74,00
	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
Ceiling, Stain, Cleaning	50,00
	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sliding door R, Chemical polution, 67 - Polish	0,00
<i>No pictures to display</i>	

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00

