



SKODA FABIA COMBI: 1PPD910

Vinnumber:	TMBJE6NWXHZ034058	Versionname:	1.4 CRTDI 55KW ACTIVE
First Registrationdate:	19/08/2016	Fiscalpower:	
Expertise Mileage:	104842	Power Kw:	55
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2312
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Luggage cover	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	No climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 T Steel			
Winter tyres:	Fr.L.	Fulda: 4 mm	Fr.R.	Fulda: 4 mm
	Re.L.	Fulda: 4 mm	Re.R.	Fulda: 4 mm

Assistance equipment





Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 897,64

Rear window, Scratch(es), E - Replace 0,00



Door R R, Scratch(es), Acceptable 0,00

Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R L, Scratch(es), E - Replace	24,00
	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
	
Roof, Scratch(es), LI - Repair and paint (complete)	385,20
	
Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), LI - Repair and paint (complete)	254,68
	
Seat cover F L, Hole, Smart repair	64,32
