



VOLKSWAGEN GOLF VII: 1LPD587

Vinnumber:	VVWZZZAUZGW153388	Versionname:	1.6 TDI 81KW TRENDLINE
First Registrationdate:	3/11/2015	Fiscalpower:	
Expertise Mileage:	128243	Power Kw:	81
Bodytype:	Berline	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1206
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Type of Tow bar
Type of GPS	Headlighting Halogen
Type of Lining	GPS big screen color
Type of climate control	Lining fabrics
	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 V Steel				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1004,10
--------------------------	----------------

Wheel cover R L, Scratch(es), E - Replace	30,00
--	--------------



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 30,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F R, Scratch(es), E - Replace 30,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Step L, Bump, Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 30,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

