



LU AUDI a3 Limousine: UK8822

Vinnumber:	WAUZZZ8V3J1023007	Versionname:	1.0 TFSI 85kW
First Registrationdate:	19/10/2017	Fiscalpower:	
Expertise Mileage:	42777	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3331
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	600,00
Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy Rims (all), Not original part, E - Replace	80,00
--	-------

