



**SKODA OCTAVIA COMBI: 1LR561**

Vinnumber:	<b>TMBJG7NE9G0118670</b>	Versionname:	<b>1.6 CRTDI 81KW GREENLINE AMBITION</b>
First Registrationdate:	<b>13/11/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>164226</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3830</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>SD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/91 H Steel</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 2 mm</b>	Fr.R.	<b>Goodyear: 2 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1646,71</b>
Door F L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	<b>30,00</b>



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F L, Scratch(es), E - Replace 30,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



Wing R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Windscreen, Stone chip(s), Acceptable 0,00



Bonnet, Dent(s), LI - Repair and paint (complete)

314,08



Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Rear spoiler, Dent(s), Acceptable

0,00

No pictures to display

Roof, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50

