



PEUGEOT PARTNER: 1LFB566

Vinnumber:	VF37B9HN0FJ740680	Versionname:	1.6 HDI 120 L1H1 55KW PACK CD AIRCO
First Registrationdate:	10/09/2015	Fiscalpower:	
Expertise Mileage:	97280	Power Kw:	55
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1215
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1401,69
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	279,15



Door moulding Lower R R, Scratch(es), E - Replace

91,50



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

280,88



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

286,76



Interior, Damaged, Acceptable

0,00



Wheel cover R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), E - Replace

398,40



Bodywork, Not original part, Acceptable

0,00



Outer door handle R R, Missing, E - Replace

20,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Wheel cover F R, Broken, E - Replace

22,50



Wheel cover F L, Deformed / Strained, E - Replace

22,50



Wing R L, Dent(s), Acceptable

0,00

No pictures to display