



BMW 4 GRAN COUPE: 1KLL091

Vinnumber:	WBA4D51070D425139	Versionname:	2.0 418D (100KW) GRAN COUPE
First Registrationdate:	28/05/2015	Fiscalpower:	
Expertise Mileage:	128233	Power Kw:	100
Bodytype:	Coupé	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1123
Maintenance:	BINNEN 27000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			743,12
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00



Wing R R, Repaired, Acceptable

0,00



Seat cover R R, Incomplete, E - Replace

10,00



Seat cover F L, Tear, Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s), It - Spot repair

115,56



Door F R, Dent(s), PDR - Paintless dent repair

162,00




Roof, Dent(s), Acceptable

0,00

No pictures to display

Bumper F L, Scratch(es), It - Spot repair

115,56



Door F L, Dent(s), Acceptable

0,00

No pictures to display