



BMW 3 GRAN TURISMO: 1LLL083

Vinnumber:	WBA8Y51070G430345	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	21/10/2015	Fiscalpower:	
Expertise Mileage:	69085	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	1900KM	Parking lot:	2223
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 W LightMetal				
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			766,56
Bumper F L, Scratch(es), It - Spot repair			115,56



Alloy rim R R, Scratch(es), Acceptable

0,00



Wing R L, Scratch(es), 67 - Polish

0,00



Wing F L, Scratch(es), Acceptable

0,00



Bumper R, Broken, Le - Replace and paint

651,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Wing R R, Dent(s), Acceptable

0,00



Roof, Dent(s), Acceptable

0,00

